HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

OH-26

Collingwood Railroad Yard Coal Tipple Between East 146th Street and East 152nd Street Cleveland Cuyahoga County Ohio

NOTE: All photographs were taken by Jet Lowe, HAER photographer, during the summer of 1979.

ON.

- OH-26-2 LOCOMOTIVE COALING TOWER. VIEW IS TOWARDS BAYS THAT STILL HOUSE REMNANTS OF THE TOWER'S CONVEYOR SYSTEM.
- OH-26-3 DETAIL VIEW OF SHELTER WHERE COAL WAS HOISTED BY CONVEYOR TO STORAGE BINS.
- OH-26-4 EAST ELEVATION. TOWER, OF REINFORCED CONCRETE CONSTRUCTION, WAS BUILT IN 1944 TO SPEED UP THE FUELING OF LOCOMOTIVE TENDERS DURING WARTIME.